

Approve UPDD kext after upgrade to MacOS 10.13.6

During our own internal testing we updated from MacOS 10.13.3 to 10.13.6 and for whatever reason it required the UPDD kext to be re-approved.

Prior to approval UPDD Daemon and the driver would not run. After approving the kext it required a reboot before all was OK.

Touch-Base Support

<http://support.touch-base.com/Knowledgebase/50543/Approve-UPDD-kext-after-u...>