A simple text based calibration utility to illustrate the basics of implementing a custom calibration program is available <u>here</u>.

A practical implementation will likely implement a GUI to show calibration targets to be touched.

Comments in the source code describe the implementation in detail.

The program also illustrates the use of event callbacks and setting a updd setting with TBApiSetSettingFromInt

Touch-Base Support <u>http://support.touch-base.com/Documentation/50424/Calibration-program</u>