

100% booting process bar

A customer reported that after installing UPDD the next boot resulted in the booting progress bar being stuck at 100%.

This was resolved by 'clearing PRAM' as described [here](#).

This is a one off report and we do not believe that this issue was caused by installing the UPDD software but we thought it would be useful to note for future reference.

Touch-Base Support

<http://support.touch-base.com/Documentation/50585/100-booting-process-bar>